2023 PRESCRIPTIVE MEASURE UPDATES

BUSINESS PROGRAMS





focus on energy

CONTENTS



Links to Measure Change Sections:

- Agribusiness
- Commercial Refrigeration
- HVAC and Plumbing
- Lighting
- Process Systems

Links to Catalogs:

- Agribusiness
- Commercial Refrigeration
- HVAC and Plumbing
- Lighting
- Process Systems

Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
AG2660	Waterer, Livestock, < 250 Watts	\$40	\$50	N/A	N/A
AG4695	LED Fixture, <155 Watts, Replacing 250 Watt HID, High Bay, Agriculture	\$45	\$55	\$45	\$55
AG4696	LED Fixture, <250 Watts, Replacing 320-399 Watt HID, High Bay, Agriculture	\$50	\$60	\$50	\$60
AG4697	LED Fixture, <250 Watts, Replacing 400 Watt HID, High Bay, Agriculture	\$75	\$70	N/A	N/A
AG4698	LED Fixture, <365 Watts, Replacing 400 Watt HID, High Bay, Agriculture	\$45	\$55	N/A	N/A
AG4701	<=180W LED, replacing or instead of 6L T8 or 4L T5HO, Agriculture	\$45	\$55	\$45	\$55
AG4702	<=250W LED, replacing or instead of 8LT8 or 6LT5HO, Agriculture	\$60	\$75	\$60	\$75



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
AG4043	VFD, Ag Primary Use Water System	\$75	\$90	\$45	\$55
AG2639	VFD, Ag Second Use Water System	\$75	\$90	\$45	\$55
AG4411	VFD, Ag Second Use Water System, Low HOU	\$50	\$50	\$30	\$30
AG4949	VFD, Variable Torque, Irrigation Well Pump, >500 HOU	\$50	\$50	\$30	\$30
AG3777	VFD, High Speed Ventilation/Circulation Fan, Ag	\$75	\$90	\$45	\$55
AG4413	VFD, High Speed Ventilation/Circulation Fan, Ag, Low HOU	\$50	\$50	\$30	\$30
AG3835	VFD, Process Pump, Agriculture	\$75	\$90	\$45	\$55
AG4414	VFD, Process Pump, Agriculture, Low HOU	\$50	\$50	\$30	\$30



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
AG3989	Refrigeration Heat Recovery, NG WH, w/ a pre-cooler and VFD on milk pump	\$600	\$750	\$600	\$750
AG3990	Refrigeration Heat Recovery, NG WH, w/ a pre-cooler	\$600	\$750	\$600	\$750
AG3991	Refrigeration Heat Recovery, NG WH, w/ no pre-cooler	\$600	\$750	\$600	\$750
AG3992	Refrigeration Heat Recovery, Elec WH, w/ a pre-cooler and VFD on milk pump	\$600	\$750	\$600	\$750
AG3993	Refrigeration Heat Recovery, Elec WH, w/ a pre-cooler	\$600	\$750	\$600	\$750
AG3994	Refrigeration Heat Recovery, Elec WH, w/ no pre-cooler	\$600	\$750	\$600	\$750



Incentive Code	Measure Name	Comments
AG4901	Grain Dryer Tune-Up	Available, removed from catalog.
AG598	Greenhouse Climate Controls	
AG5088	Ventilation Fan, High-Speed High-Efficiency, Fixed Speed, ≥ 48 inches, Dairy	



COMMERCIAL REFRIGERATION

Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
R2306	ECM Compressor Fan Motor	\$25	\$30	\$25	\$30
R2307	ECM Condenser/Condensing Unit Fan Motor	\$25	\$30	\$25	\$30
R2308	ECM Evaporator Fan Motor, Walk-in Cooler, <1/20hp	\$25	\$30	N/A	N/A
R2309	ECM Evaporator Fan Motor, Walk-in Cooler, 1/20hp - 1 hp	\$50	\$60	N/A	N/A
R2310	ECM Evaporator Fan Motor, Walk-in Freezer, <1/20hp	\$25	\$30	N/A	N/A
R2311	ECM Evaporator Fan Motor, Walk-in Freezer, 1/20hp - 1 hp	\$50	\$60	N/A	N/A
R2312	ECM Motor, Cooler/Freezer Case	\$25	\$30	\$25	\$30



COMMERCIAL REFRIGERATION

Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
R2509	Reach In Refrigerated Case w/ Doors replacing Open Multi Deck Case	\$80	\$100	\$55	\$60
R3409	Retrofit Open Refrigerated Cases with Doors	\$60	\$70	\$40	\$50
R2269	Cooler Evaporator Fan Control	\$15	\$18	\$10	\$12
R4759	Evaporator Fan Control, Reach-in Cooler or Freezer	\$15	\$18	\$10	\$12



COMMERCIAL REFRIGERATION

Discontinued Measures

Incentive Code	Measure Name	Comments
R2197	Anti-sweat Heater Controls, Freezer Case, Low-heat Door	Replaced with measure R5439
R2198	Anti-sweat Heater Controls, Freezer Case, No-heat Door	Replaced with measure R5439
R2199	Anti-sweat Heater Controls, Freezer Case, Standard Door	Replaced with measure R5439
R2200	Anti-sweat Heater Controls, Refrigerated Case, Low-heat or No-heat Door	Replaced with measure R5440
R2201	Anti-sweat Heater Controls, Refrigerated Case, Standard Door	Replaced with measure R5440

Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construction Incentive 2023
R5439	Anti-sweat Heater Controls, Freezer Case	\$25	N/A
R5440	Anti-sweat Heater Controls, Refrigerated Case	\$25	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
H2218	Boiler, Hot Water, Modulating, >=90% AFUE, < 300 mbh	\$4	\$5	\$4	\$5
H3276	Boiler, Hot Water, Condensing, >=90% AFUE, >=300 mbh	\$4	\$5	\$4	\$5
H3491	Furnace with ECM, ≥95%+ AFUE, NG	\$220	\$270	\$180	\$220
H3492	Furnace with ECM, ≥90%+ AFUE, NG	\$100	\$120	\$80	\$100
H5081	Direct Fired Make-up Air Unit	\$0.20	\$0.25	\$0.15	\$0.15
H2221	Boiler, Outside Temperature Reset/Cutout Control	\$60	\$70	N/A	N/A
H2205	Boiler Control, Linkageless	\$15	\$18	N/A	N/A
H2203	Boiler Burner, 10:1 High Turn Down	\$10	\$12	N/A	N/A
H5237	Boiler Burner, 10:1 High Turn Down, New Boiler	\$10	\$12	\$10	\$12



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
H2225	Steam Trap Survey	\$4	\$5	N/A	N/A
H4004	Steam Trap Repair, < 10 psig, General Heating, 7/32" or Smaller	\$30	\$35	N/A	N/A
H4005	Steam Trap Repair, < 10 psig, General Heating, 1/4"	\$30	\$35	N/A	N/A
H4006	Steam Trap Repair, < 10 psig, General Heating, 5/16"	\$30	\$35	N/A	N/A
H4007	Steam Trap Repair, < 10 psig, General Heating, 3/8" or Larger	\$30	\$35	N/A	N/A
H4008	Steam Trap Repair, 10-49 psig, General Heating, 7/32" or Smaller	\$50	\$60	N/A	N/A
H4009	Steam Trap Repair, 10-49 psig, General Heating, 1/4"	\$50	\$60	N/A	N/A
H4010	Steam Trap Repair, 10-49 psig, General Heating, 5/16"	\$50	\$60	N/A	N/A
H4011	Steam Trap Repair, 10-49 psig, General Heating, 3/8" or Larger	\$50	\$60	N/A	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
H4012	Steam Trap Repair, 50-124 psig, General Heating, 7/32" or Smaller	\$75	\$90	N/A	N/A
H4013	Steam Trap Repair, 50-124 psig, General Heating, 1/4"	\$75	\$90	N/A	N/A
H4014	Steam Trap Repair, 50-124 psig, General Heating, 5/16"	\$75	\$90	N/A	N/A
H4015	Steam Trap Repair, 50-124 psig, General Heating, 3/8" or Larger	\$75	\$90	N/A	N/A
H4944	≥125 psig General Heating Steam Trap, ≤ 7/32" Orifice	\$125	\$150	N/A	N/A
H4945	≥125 psig General Heating Steam Trap, 1/4" Orifice	\$125	\$150	N/A	N/A
H4946	≥125 psig General Heating Steam Trap, 5/16" Orifice	\$125	\$150	N/A	N/A
H4947	≥125 psig General Heating Steam Trap, ≥ 3/8" Orifice	\$125	\$150	N/A	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
H3910	ECM HVAC Fan Motors, Heating	\$25	\$30	N/A	N/A
H3911	ECM HVAC Fan Motors, Cooling	\$25	\$30	N/A	N/A
H3912	ECM HVAC Fan Motors, Occupied Ventilation	\$25	\$30	N/A	N/A
H3913	ECM HVAC Fan Motors, 24/7 Ventilation	\$25	\$30	N/A	N/A
H3266	Demand Control Ventilation, RTU Optimization	\$350	\$430	\$350	\$430
H4375	Smart Thermostat, Natural Gas Boiler	\$50	\$60	\$50	\$60
H4376	Smart Thermostat, Natural Gas Furnace w/ AC	\$50	\$60	\$50	\$60
H4377	Smart Thermostat, Natural Gas Rooftop Unit w/ AC	\$50	\$60	\$50	\$60
H5080	Smart Thermostat, Natural Gas Unit Heater, ≥ 90% Thermal Efficiency	\$50	\$60	\$50	\$60
H5079	Smart Thermostat, Natural Gas Unit Heater, Standard Efficiency	\$50	\$60	\$50	\$60



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
H2429	Insulation, Steam Fitting, Removable, NG	\$8.00	\$10.00	N/A	N/A
H2430	Insulation, Steam Piping, NG	\$2.00	\$2.50	N/A	N/A
H2314	Energy Recovery Ventilator	\$0.75	\$0.90	\$0.60	\$0.70
H5082	Energy Recovery Ventilator, Sensible Heat Only	\$0.65	\$0.80	\$0.50	\$0.50
H2640	VFD, Boiler Draft Fan	\$35	\$40	\$25	\$30
H2641	VFD, Cooling Tower Fan	\$35	\$40	\$25	\$30
H2643	VFD, HVAC Fan	\$35	\$40	\$25	\$30
H2644	VFD, HVAC Heating Pump	\$35	\$40	\$25	\$30
H2646	VFD, Pool Pump Motor	\$35	\$40	\$25	\$30
H2726	VFD, Chilled Water Distribution Pump	\$35	\$40	\$25	\$30



Incentive Code	Measure Name	Comments
H5234	Boiler, 95%+ Efficient, With DHW, Multifamily, NG	Available through Multifamily
H3277	Boiler, Hot Water, Near Condensing, >=85% AFUE, >=300 mbh	Discontinued
H3066	Economizer, RTU Optimization	Discontinued
H4905	Modulating Commercial Dryer Controls, Large Capacity High Use	Discontinued
H4904	Modulating Commercial Dryer Controls, Large Capacity Low Use	Discontinued
H4903	Modulating Commercial Dryer Controls, Small Capacity High Use	Discontinued
H4902	Modulating Commercial Dryer Controls, Small Capacity Low Use	Discontinued



Incentive Code	Measure Name	Comments
P3045	Water Heater, High Usage, >=90% TE, NG	Available through Midstream
P4942	Water Heater, High Usage >= 90% Thermal Efficiency, Tankless, NG	Available through Midstream
P5083	Water Heater, High Usage, ≥ 95% TE, K-12 School, NG	Available through Midstream
K2621	Ventilation Controls, Kitchen Hood, Temp only, Adder for MUA, Retrofit	Available through Midstream
K2623	Ventilation Controls, Kitchen Hood, Temp only, Exhaust Only, Retrofit	Available through Midstream
K2625	Ventilation Controls, Kitchen Hood, with Optical, Adder for MUA, Retrofit	Available through Midstream
K2627	Ventilation Controls, Kitchen Hood, with Optical, Exhaust Only, Retrofit	Available through Midstream



Discontinued Measures

Incentive Code	Measure Name	Comments			
H4741	A/C Single Package, ≤ 65 MBh, SEER 16	Use H5423 for SEER2 16 equivalent measure (split and packaged)			
H4742	A/C Single Package, ≤ 65 MBh, SEER 17	Use H5424 for SEER2 17 equivalent measure (split and packaged)			
H4743	A/C Single Package, ≤ 65 MBh, SEER 18	Use H5425 for SEER2 18 equivalent measure (split and packaged)			
H5071	A/C Single Package, ≤ 65 MBh, SEER 19	Use H5426 for SEER2 19 equivalent measure (split and packaged)			
H5072	A/C Single Package, ≤ 65 MBh, SEER 20	Use H5427 for SEER2 20 equivalent measure (split and packaged)			
H4737	A/C Split System, ≤ 65 MBh, SEER 16	Use H5423 for SEER2 16 equivalent measure (split and packaged)			
H4738	A/C Split System, ≤ 65 MBh, SEER 17	Use H5424 for SEER2 17 equivalent measure (split and packaged)			
H4739	A/C Split System, ≤ 65 MBh, SEER 18	Use H5425 for SEER2 18 equivalent measure (split and packaged)			
H5069	A/C Split System, ≤ 65 MBh, SEER 19	Use H5426 for SEER2 19 equivalent measure (split and packaged)			
H5070	A/C Split System, ≤ 65 MBh, SEER 20	Use H5427 for SEER2 20 equivalent measure (split and packaged)			
Learn more about the January 1 2023 SEED2 requirements at seer2 com					

Learn more about the January 1, 2023, SEER2 requirements at seer2.com





Incentive Code	Measure Name	Comments		
H4745	Air-Source Heat Pump, ≤ 65 MBh, SEER 16 and 9.0 HSPF	Use H5483 for SEER2 16 equivalent measure		
H4746	Air-Source Heat Pump, ≤ 65 MBh, SEER 17 and 9.0 HSPF	Use H5429 for SEER2 17 equivalent measure		
H4747	Air-Source Heat Pump, ≤ 65 MBh, SEER 18 and 9.0 HSPF	Use H5430 for SEER2 18 equivalent measure		
H5073	Air-Source Heat Pump, ≤ 65 MBh, SEER 19 and 9.0 HSPF	Use H5431 for SEER2 19 equivalent measure		
H5074	Air-Source Heat Pump, ≤ 65 MBh, SEER 20 and 9.0 HSPF	Use H5432 for SEER2 20 equivalent measure		
Learn more about the January 1, 2023, SEER2 requirements at seer2.com				



Incentive Code	Measure Name	Comments
H4753	Unit Heater, ≥90% Thermal Efficiency, Heating Setpoint = 70°F	Replaced with measure H5436
H4754	Unit Heater, ≥90% Thermal Efficiency, Heating Setpoint = 65°F	Replaced with measure H5436
H4755	Unit Heater, ≥90% Thermal Efficiency, Heating Setpoint = 60°F	Replaced with measure H5436
H4756	Unit Heater, ≥90% Thermal Efficiency, Heating Setpoint = 55°F	Replaced with measure H5436
B3680	Spring-loaded Garage Door Hinge, 55 Degree Indoor Temperature Setpoint	Replaced with measure B5438
B3681	Spring-loaded Garage Door Hinge, 60 Degree Indoor Temperature Setpoint	Replaced with measure B5438
B3682	Spring-loaded Garage Door Hinge, 65 Degree Indoor Temperature Setpoint	Replaced with measure B5438
B3683	Spring-loaded Garage Door Hinge, 70 Degree Indoor Temperature Setpoint	Replaced with measure B5438



Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construction Incentive 2023
H5423	A/C Split System or Single Package, ≤ 65 MBh, SEER2 16	\$40	\$30
H5424	A/C Split System or Single Package, ≤ 65 MBh, SEER2 17	\$60	\$40
H5425	A/C Split System or Single Package, ≤ 65 MBh, SEER2 18	\$80	\$50
H5426	A/C Split System or Single Package, ≤ 65 MBh, SEER2 19	\$100	\$60
H5427	A/C Split System or Single Package, ≤ 65 MBh, SEER2 20	\$120	\$70
H5428	Air-Source Heat Pump, Split System, ≤ 65 MBh, SEER2 16 and 8.5 HSPF2	\$65	\$45
H5429	Air-Source Heat Pump, Split System, ≤ 65 MBh, SEER2 17 and 8.5 HSPF2	\$85	\$55
H5430	Air-Source Heat Pump, Split System, ≤ 65 MBh, SEER2 18 and 8.5 HSPF2	\$105	\$65
H5431	Air-Source Heat Pump, Split System, ≤ 65 MBh, SEER2 19 and 8.5 HSPF2	\$125	\$75
H5432	Air-Source Heat Pump, Split System, ≤ 65 MBh, SEER2 20 and 8.5 HSPF2	\$145	\$85



Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construction Incentive 2023
H5435	Smart Switched Reluctance Motor, Supply Fan	\$40	N/A
B5438	Spring-loaded Garage Door Hinge	\$100	\$80
H5436	Unit Heater, ≥90% Thermal Efficiency	\$2.50	\$1.25



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
L3091	LED Fixture, <155 Watts, Replacing 250 Watt HID, High Bay	\$30	\$35	N/A	N/A
L3092	LED Fixture, <250 Watts, Replacing 320-400 Watt HID, High Bay	\$35	\$40	N/A	N/A
L3093	LED Fixture, <250 Watts, Replacing 400 Watt HID, High Bay	\$50	\$60	N/A	N/A
L3094	LED Fixture, <365 Watts, Replacing 400 Watt HID, High Bay	\$30	\$35	N/A	N/A
L3095	LED Fixture, <500 Watts, Replacing 1000 Watt HID, High Bay	\$80	\$100	N/A	N/A
L3096	LED Fixture, <800 Watts, Replacing 1000 Watt HID, High Bay	\$50	\$60	N/A	N/A
L4795	LED Fixture, ≤ 300 Watts, Replacing 10-Lamp T8 or 8-Lamp T5HO, High Bay	\$50	\$60	N/A	N/A
L4796	LED Fixture, ≤ 350 Watts, Replacing 12-Lamp T8 or 10-Lamp T5HO, High Bay	\$65	\$80	N/A	N/A
L4347	LED Fixture, ≤250 Watts, Replacing 8-lamp T8 or 6-lamp T5HO, High Bay	\$35	\$40	N/A	N/A
L3393	LED Fixture,<=180 Watts, Replacing 4 lamp T5 or 6 lamp T8, High Bay	\$25	\$30	N/A	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
L3111	LED Troffer, 2x4, Replacing 4' 3-4 Lamp T8 Troffer	\$15	\$18	N/A	N/A
L4282	LED, Exterior Fixture, High Output, 10,000-29,999 lumens	\$50	\$60	\$50	\$50
L4280	LED, Exterior Fixture, Low Output, <= 4,999 lumens	\$15	\$18	\$10	\$10
L4281	LED, Exterior Fixture, Mid Output, 5,000-9,999 lumens	\$25	\$30	\$20	\$20
L4283	LED, Exterior Fixture, Very High Output, >= 30,000 lumens	\$120	\$150	\$100	\$120



Discontinued Measures

Incentive Code	Measure Name	Comments
L3934	LED Lamp, ENERGY STAR, Replacing Interior Directional CFL, ≤ 13W	Discontinued
L3932	LED Lamp, ENERGY STAR, Replacing Interior Directional CFL, ≥ 23W CFL	Discontinued
L3933	LED Lamp, ENERGY STAR, Replacing Interior Directional CFL, 14W-22W CFL	Discontinued
L3946	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, ≤ 35W	Discontinued
L3942	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, 100W – 119W	Discontinued
L3941	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, 120W – 250W	Discontinued
L3945	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, 36W – 54W	Discontinued
L3944	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, 55W – 74W	Discontinued
L3943	LED Lamp, ENERGY STAR, Replacing Interior Directional Incandescent, 75W – 99W	Discontinued



Discontinued Measures

Incentive Code	Measure Name	Comments
L5227	Decorative Exterior LED with rated lumen output of 1,100-1,599 replacing incandescent or CFL	Discontinued
L5226	Decorative Exterior LED with rated lumen output of 1,600-1,999 replacing incandescent or CFL	Discontinued
L5230	Decorative Exterior LED with rated lumen output of 250-449 replacing incandescent or CFL	Discontinued
L5229	Decorative Exterior LED with rated lumen output of 450-799 replacing incandescent or CFL	Discontinued
L5228	Decorative Exterior LED with rated lumen output of 800-1,099 replacing incandescent or CFL	Discontinued
L5217	Decorative Interior LED with rated lumen output of 1,100-1,599 replacing incandescent or CFL	Discontinued
L5216	Decorative Interior LED with rated lumen output of 1,600-1,999 replacing incandescent or CFL	Discontinued
L5220	Decorative Interior LED with rated lumen output of 250-449 replacing incandescent or CFL	Discontinued
L5219	Decorative Interior LED with rated lumen output of 450-799 replacing incandescent or CFL	Discontinued
L5218	Decorative Interior LED with rated lumen output of 800-1,099 replacing incandescent or CFL	Discontinued



Discontinued Measures

Incentive Code	Measure Name	Comments
L5222	Omnidirectional Exterior LED with rated lumen output of 1,100-1,599 replacing incandescent or CFL	Discontinued
L5221	Omnidirectional Exterior LED with rated lumen output of 1,600-1,999 replacing incandescent or CFL	Discontinued
L5225	Omnidirectional Exterior LED with rated lumen output of 250-449 replacing incandescent or CFL	Discontinued
L5224	Omnidirectional Exterior LED with rated lumen output of 450-799 replacing incandescent or CFL	Discontinued
L5223	Omnidirectional Exterior LED with rated lumen output of 800-1,099 replacing incandescent or CFL	Discontinued
L5212	Omnidirectional Interior LED with rated lumen output of 1,100-1,599 replacing incandescent or CFL	Discontinued
L5211	Omnidirectional Interior LED with rated lumen output of 1,600-1,999 replacing incandescent or CFL	Discontinued
L5215	Omnidirectional Interior LED with rated lumen output of 250-449 replacing incandescent or CFL	Discontinued
L5214	Omnidirectional Interior LED with rated lumen output of 450-799 replacing incandescent or CFL	Discontinued
L5213	Omnidirectional Interior LED with rated lumen output of 800-1,099 replacing incandescent or CFL	Discontinued



Incentive Code	Measure Name	Comments
L3931	LED Lamp, ENERGY STAR, Replacing Exterior Directional CFL, ≤ 13W	Discontinued
L3929	LED Lamp, ENERGY STAR, Replacing Exterior Directional CFL, ≥ 23W CFL	Discontinued
L3930	LED Lamp, ENERGY STAR, Replacing Exterior Directional CFL, 14W-22W CFL	Discontinued
L3940	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, ≤ 35W Incandescent	Discontinued
L3936	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, 100W – 119W Incandescent	Discontinued
L3935	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, 120W – 250W Incandescent	Discontinued
L3939	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, 36W – 54W Incandescent	Discontinued
L3938	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, 55W – 74W Incandescent	Discontinued
L3937	LED Lamp, ENERGY STAR, Replacing Exterior Directional Incandescent, 75W – 99W Incandescent	Discontinued





Incentive		
Code	Measure Name	Comments
L4797	LED Replacement of 2' T8 or T12 Lamp w/External Driver (UL Type C)	Replaced with measure L5453
L4799	LED Replacement of 2' T8 or T12 Lamp Utilizing Existing Ballast (UL Type A)	Replaced with measure L5453
L4798	LED Replacement of 2' T8 or T12 Lamp, Direct Wire (UL Type B)	Replaced with measure L5453
L3760	LED Troffer, 1x4, Replacing 4' 1-2 Lamp T8 Troffer	Replaced with measure L5459
L4793	LED Troffer, 2x4, Replacing 4' 1-2 Lamp T8 Troffer	Replaced with measure L5445



Incentive		
Code	Measure Name	Comments
L3738	LED Fixture, Linear Ambient, Replacing 1 or 2 T5 lamp(s) in Cross Section	Replaced with measure L5445
L4786	LED Fixture, Linear Ambient, Replacing 1 or 2 T5 lamp(s) in Cross Section, Exterior, 12 hour	Replaced with measure L5446
L4785	LED Fixture, Linear Ambient, Replacing 1 or 2 T5 lamp(s) in Cross Section, Exterior, 24 hour	Replaced with measure L5447
L3740	LED Fixture, Linear Ambient, Replacing 1 or 2 T8/T12 lamp(s) in Cross Section	Replaced with measure L5445
L4782	LED Fixture, Linear Ambient, Replacing 1 or 2 T8/T12 lamp(s) in Cross Section, Exterior, 12 hour	Replaced with measure L5445
L4781	LED Fixture, Linear Ambient, Replacing 1 or 2 T8/T12 lamp(s) in Cross Section, Exterior, 24 hour	Replaced with measure L5446



Incentive		
Code	Measure Name	Comments
L3739	LED Fixture, Linear Ambient, Replacing 3 or 4 T5 lamps in Cross Section	Replaced with measure L5448
L3741	LED Fixture, Linear Ambient, Replacing 3 or 4 T8/12 lamps in Cross Section	Replaced with measure L5448
L4788	LED Fixture, Linear Ambient, Replacing 3 or 4 T5 lamps in Cross Section, Exterior, 12 hour	Replaced with measure L5449
L4784	LED Fixture, Linear Ambient, Replacing 3 or 4 T8/T12 lamps in Cross Section, Exterior, 12 hour	Replaced with measure L5449
L4787	LED Fixture, Linear Ambient, Replacing 3 or 4 T5 lamps in Cross Section, Exterior, 24 hour	Replaced with measure L5450
L4783	LED Fixture, Linear Ambient, Replacing 3 or 4 T8/T12 lamps in Cross Section, Exterior, 24 hour	Replaced with measure L5450



Discontinued Measures

Incentive		
Code	Measure Name	Comments
L3512	LED Replacement of 4' T8 Lamps utilizing existing ballast	Replaced with measure L5451
L3511	LED Replacement of 4' T8 Lamps w/Integral or External Driver	Replaced with measure L5451
L3759	LED Replacement of 4' T8 Lamps, Direct Wire	Replaced with measure L5451
L4803	LED Replacement of 4' T5 Lamp w/External Driver (UL Type C)	Replaced with measure L5451
L4807	LED Replacement of 4' T5 Lamp Utilizing Existing Ballast (UL Type A)	Replaced with measure L5451
L4805	LED Replacement of 4' T5 Lamp, Direct Wire (UL Type B)	Replaced with measure L5451
L4800	LED Replacement of U-Bend T8 or T12 Lamp w/External Driver (UL Type C)	Replaced with measure L5451
L4802	LED Replacement of U-Bend T8 or T12 Lamp Utilizing Existing Ballast (UL Type A)	Replaced with measure L5451
L4801	LED Replacement of U-Bend T8 or T12 Lamp, Direct Wire (UL Type B)	Replaced with measure L5451



Discontinued Measures

la continu		
Incentive Code	Measure Name	Comments
L4348	LED Replacement of 4-Foot T8 Lamps Utilizing Existing Ballast, Exterior	Replaced with measure L5456
L4350	LED Replacement of 4-Foot T8 Lamps, Direct Wire, Exterior	Replaced with measure L5456
L4352	LED Replacement of 4-Foot T8 Lamps, w/External Driver, Exterior	Replaced with measure L5456
L4349	LED Replacement of 4-Foot T8 Lamps Utilizing Existing Ballast, Exterior, 24/7	Replaced with measure L5455
L4351	LED Replacement of 4-Foot T8 Lamps, Direct Wire, Exterior, 24/7	Replaced with measure L5455
L4353	LED Replacement of 4-Foot T8 Lamps, w/External Driver, Exterior, 24/7	Replaced with measure L5455
L4804	LED Replacement of 4' T5HO Lamp w/External Driver (UL Type C)	Replaced with measure L5452
L4808	LED Replacement of 4' T5HO Lamp Utilizing Existing Ballast (UL Type A)	Replaced with measure L5452
L4806	LED Replacement of 4' T5HO Lamp, Direct Wire (UL Type B)	Replaced with measure L5452



Discontinued Measures

la continu		
Incentive Code	Measure Name	Comments
L4809	LED Replacement of 8' T8 or T12 Lamp w/External Driver (UL Type C)	Replaced with measure L5454
L4811	LED Replacement of 8' T8 or T12 Lamp Utilizing Existing Ballast (UL Type A)	Replaced with measure L5454
L4810	LED Replacement of 8' T8 or T12 Lamp, Direct Wire (UL Type B)	Replaced with measure L5454
L4834	LED Replacement of 8' T8 or T12 Lamp w/External Driver (UL Type C), Exterior 24/7	Replaced with measure L5457
L4833	LED Replacement of 8' T8 or T12 Lamp w/External Driver (UL Type A), Exterior 24/7	Replaced with measure L5457
L4835	LED Replacement of 8' T8 or T12 Lamp, Direct Wire (UL Type B), Exterior 24/7	Replaced with measure L5457
L4831	LED Replacement of 8' T8 or T12 Lamp w/External Driver (UL Type C), Exterior	Replaced with measure L5458
L4830	LED Replacement of 8' T8 or T12 Lamp w/External Driver (UL Type A), Exterior	Replaced with measure L5458
L4832	LED Replacement of 8' T8 or T12 Lamp, Direct Wire (UL Type B), Exterior	Replaced with measure L5458



Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construction Incentive 2023
L5461	LED Fixture, ≤ 125 Watts, Replacing 4 Lamp 4' or 2 Lamp 8' T12HO, High Bay	\$20	N/A
L5460	LED Fixture, ≤ 85 Watts, Replacing 4 Lamp 4' or 2 Lamp 8' T8 or T12, High Bay	\$10	N/A
L5445	LED Fixture, Linear Ambient, Replacing 1 or 2 Lamp(s) in Cross Section	\$1	N/A
L5446	LED Fixture, Linear Ambient, Replacing 1 or 2 Lamp(s) in Cross Section, Exterior	\$2	\$1
L5447	LED Fixture, Linear Ambient, Replacing 1 or 2 Lamp(s) in Cross Section, Exterior 24/7	\$2	\$1
L5448	LED Fixture, Linear Ambient, Replacing 3 or 4 Lamps in Cross Section	\$2.50	N/A
L5449	LED Fixture, Linear Ambient, Replacing 3 or 4 Lamps in Cross Section, Exterior	\$5	\$3
L5450	LED Fixture, Linear Ambient, Replacing 3 or 4 Lamps in Cross Section, Exterior 24/7	\$5	\$3
L5459	LED Troffer, 1x4 or 2x4, Replacing 4' 1 or 2 Lamp T8 Troffer	\$4	N/A



Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construction Incentive 2023
L5453	2' TLED, Replacing 2' T8 or T12 Lamp, Interior	\$1.25	N/A
L5456	4' or U-Bend TLED, ≤24W, Replacing 4' or U-Bend T5, T8 or T12 Lamp, Exterior	\$1.50	N/A
L5455	4' or U-Bend TLED, ≤24W, Replacing 4' or U-Bend T5, T8 or T12 Lamp, Exterior 24/7	\$1.50	N/A
L5451	4' or U-Bend TLED, ≤24W, Replacing 4' or U-Bend T5, T8 or T12 Lamp, Interior	\$1.50	N/A
L5452	4' TLED, Replacing 4' T5HO Lamp, Interior	\$3	N/A
L5458	8' TLED, Replacing 8' T8 or T12 Lamp, Exterior	\$3	N/A
L5457	8' TLED, Replacing 8' T8 or T12 Lamp, Exterior 24/7	\$3	N/A
L5454	8' TLED, Replacing 8' T8 or T12 Lamp, Interior	\$3	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
PS4766	Compressed Air System Leak Survey and Repair	\$4	\$5	N/A	N/A
PS2196	Air Compressor, Variable Speed Drive, Constant Speed Replacement	\$40	\$50	\$40	\$50
PS4362	VSD Vacuum Pump, ≤ 30 hp, Constant Torque	\$30	\$35	\$30	\$35
PS2264	Compressed Air, Cycling Thermal Mass Air Dryers	\$0.50	\$1	\$0.50	\$1
PS4363	Dew Point Controls for Desiccant Dryers	\$2	\$2.50	\$2	\$2.50
PS2259	Compressed Air Nozzles, Air Entraining	\$8	\$10	\$8	\$10
PS4761	Process Boiler Control, Linkageless	\$15	\$18	N/A	N/A
PS4760	Process Boiler Burner, 10:1 High Turn Down	\$10	\$12	N/A	N/A
PS5238	Process Boiler Burner, 10:1 High Turn Down, New Boiler	\$10	\$12	\$10	\$12



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
PS4041	Steam Trap Survey, Industrial	\$4	\$5	N/A	N/A
PS3999	Steam Trap Repair, < 10 psig, Industrial	\$30	\$35	N/A	N/A
PS4000	Steam Trap Repair, 10-49 psig, Industrial	\$50	\$60	N/A	N/A
PS4001	Steam Trap Repair, 50-124 psig, Industrial	\$75	\$90	N/A	N/A
PS4002	Steam Trap Repair, 125-225 psig, Industrial	\$125	\$150	N/A	N/A
PS4003	Steam Trap Repair, > 225 psig, Industrial	\$200	\$250	N/A	N/A



Incentive Rate Changes

Incentive Code	Measure Name	Retrofit Incentive 2022	Retrofit Incentive 2023	New Construction Incentive 2022	New Construction Incentive 2023
PS2726	VFD, Chilled Water Distribution Pump	\$30	\$40	\$25	\$30
PS2640	VFD, Boiler Draft Fan	\$30	\$40	\$25	\$30
PS2641	VFD, Cooling Tower Fan	\$30	\$40	\$25	\$30
PS2647	VFD, Process Fan	\$30	\$40	\$25	\$30
PS2648	VFD, Process Pump	\$30	\$40	\$25	\$30
PS3280	VFD, Constant Torque	\$30	\$35	N/A	N/A
PS4765	Battery Charger, Industrial, High Frequency	\$3	\$3.75	\$3	\$3.75
PS3244	Process Exhaust Filtration	\$0.55	\$0.60	N/A	N/A
PS2257	Compressed Air Heat Recovery, Space Heating	\$50	\$60	\$50	\$60
PS3928	Vacuum Pump Heat Recovery, Space Heating	\$50	\$60	\$50	\$60



Discontinued Measures

la contina		
Incentive Code	Measure Name	Comments
PS4769	A/C Split System, ≤ 65 MBh, SEER 16, Data Center/Telecom	Discontinued
PS4770	A/C Split System, ≤ 65 MBh, SEER 17, Data Center/Telecom	Discontinued
PS4771	A/C Split System, ≤ 65 MBh, SEER 18, Data Center/Telecom	Discontinued
PS5075	A/C Split System, ≤ 65 MBh, SEER 19, Data Center/Telecom	Discontinued
PS5076	A/C Split System, ≤ 65 MBh, SEER 20, Data Center/Telecom	Discontinued
PS4773	A/C Single Package, ≤ 65 MBh, SEER 16, Data Center/Telecom	Discontinued
PS4774	A/C Single Package, ≤ 65 MBh, SEER 17, Data Center/Telecom	Discontinued
PS4775	A/C Single Package, ≤ 65 MBh, SEER 18, Data Center/Telecom	Discontinued
PS5077	A/C Single Package, ≤ 65 MBh, SEER 19, Data Center/Telecom	Discontinued
PS5078	A/C Single Package, ≤ 65 MBh, SEER 20, Data Center/Telecom	Discontinued



Added Measures

Incentive Code	Measure Name	Retrofit Incentive 2023	New Construc tion Incentive 2023
PS5441	Desiccant Compressed Air Dryer, Heated	\$2	\$2
PS5442	Desiccant Compressed Air Dryer, Blower Purge	\$2	\$2
PS5443	Desiccant Compressed Air Dryer, Zero Purge	\$2	\$2
PS5444	Compressed Air Storage, Increase from ≤ 1 Gal/CFM to ≥ 3 Gal/CFM	\$20	\$20

